

Firmware Policy

chroma+scan 3XXX

- 1. It is possible to mix sensor firmware versions in a system as per the table below without having to apply a complete system firmware update.
- 2. LMI no longer supports 4.10.X.X firmware; all systems must be upgraded to 4.11.6.2 or higher for support.
- 3. Once you are running 4.11.X.X firmware you can upgrade or downgrade your firmware version.
- 4. LMI requires that the sensor and station firmware match for long-term stability of the sensor network.
- 5. For quick replacement of a failed sensor
 - i. Remove failed sensor from frame
 - ii. Replace with a sensor using a firmware version that is compatible with your station firmware (see below)
 - iii. Calibrate the system
 - iv. Start running the system
 - v. At the next available maintenance time, upgrade the entire system to a single firmware version

		New Sensor Firmware **					
		4.10.X.X	4.11.6.22	4.11.11.31 and 4.11.11.50	4.11.12.8	4.11.12.23	4.11.12.23 (330xA only)
Current System Firmware *	4.10.XX	✓	×	×	*	×	×
	4.11.6.22	*	✓	×	×	*	*
	4.11.11.31 and 4.11.11.50	*	×	✓	✓	✓	*
	4.11.12.8	×	×	✓	✓	✓	*
	4.11.12.23	*	×	✓	✓	✓	✓

^{*}The firmware currently running on your system

^{**}Adding a new, repaired or spare sensor to the system

